

## **GASKET CUTTING**

Conventional methods should be used when cutting non-metallic gaskets such as oscillating knife, water-jet, steel punch dies, etc.

Avoid creating large amounts of dust. The use of grinders, dull razors, or hammers is not recommended.

The ability of a gasket to make and maintain a seal depends not only on the style and quality of the gasket material, but also on medium being sealed, the flange design, the amount of pressure applied to the gasket by the bolts and how the gasket is assembled onto the flanges and tightened. These factors are beyond the manufacturer's control.

**KLINGER Thermoseal** 

2350 Campbell Road, Sidney, Ohio 45365

Tel: +1 937 498 2222